

Quality Code	Quality Clause Title
Q-001	Flow Down Requirements
Q-002	Quality System
Q-003	Discrepancies
Q-004	FOD Foreign Object Debris/Damage Program
Q-005	ESD Electrostatic Discharge Control Program
Q-006	Cleanliness
Q-007	Approved Suppliers
Q-008	Approved Process
Q-009	Supplier Design / Process Changes
Q-010	Key Characteristics
Q-011	Certificate of Calibration
Q-012	Acceptance Test Plan
Q-013	Right of Access
Q-014	Standards of Workmanship
Q-015	Fracture Critical Control
Q-016	Surveillance
Q-017	Source Inspection
Q-018	Nondestructive Inspection
Q-019	Destructive Analysis
Q-020	Government Source Inspection
Q-021	First Article Inspection
Q-022	Digital Data
Q-023	Raw Material Test Reports
Q-024	Objective Evidence of Dimensional Inspection
Q-025	Corrective Action
Q-026	Supplier Product Nonconformance
Q-027	Certificate of Compliance
Q-028	Limited Life Material
Q-029	Part Identification / Traceability
Q-030	Packaging and Handling
Q-031	Counterfeit Goods
Q-032	ITAR Registration
Q-033	Records Retention
Q-034	Safety and Health Plan
Q-035	Government Furnished Property
Q-036	Safety Data Sheet (SDS)
Q-037	Certificate of Analysis
Q-038	Specifications



Quality Clauses F-740-006 Rev. J

Q-001 Flow Down Requirements

The supplier and all in the supply chain shall flow down to their suppliers the applicable requirements of this purchase order, including any key characteristics. Suppliers are required to apply appropriate controls to their direct and sub-tier external providers to ensure requirements of the purchase order are met.

Q-002 Quality System

The supplier is required to maintain a quality management system to ensure quality of product and/or service. The quality management system may be subject to a quality review by Bigelow Aerospace. Personnel providing a product or service under this purchase order or contract must ensure personnel awareness of their contribution to product or service conformity, product safety, and the importance of ethical behavior.

Q-003 <u>Discrepancies</u>

During performance against this purchase order, any deviations noted from established drawings must be reported to the buyer immediately. No deviation will be considered approved without written confirmation of the fact from buyer. Under no circumstances are changes or repairs to be undertaken without written approval from buyer.

Q-004 FOD Foreign Object Debris / Damage Program

The supplier shall develop and maintain a Foreign Object Debris/Damage FOD) prevention program to prevent introduction of foreign objects into any item delivered under this purchase order.

Q-005 ESD Electrostatic Discharge Control Program

The supplier shall develop and maintain an ESD control program that meets the requirements to the latest revision of JEDEC Standard JESD625 and includes documented employee training.

Q-006 Cleanliness

Cleanliness levels for all hardware shall be identified on all engineering drawings. Handling, Cleaning, and Encapsulation of material can be performed in a facility that is environmentally controlled to class 100,000 conditions or better, or to the requirement identified in writing.



Quality Clauses F-740-006 Rev. J

Q-007 Approved Suppliers

Supplier must maintain a record of approved suppliers that includes status of approval and scope of approval.

Q-008 Approved Process

All processing shall be accomplished by NADCAP or Bigelow Aerospace approved process suppliers. Processes specified on Bigelow Aerospace drawings must be performed by sources listed on the Bigelow Aerospace Approved Supplier List.

Q-009 Supplier Design / Process Changes

The Supplier shall notify and obtain written approval from Bigelow Aerospace for changes in design, manufacturing, assembly processes, location or source of supply of their products.

Q-010 Key Characteristics

Statistical Process Control is required on this Purchase Order. The supplier shall identify the statistical techniques in establishing, controlling and verifying process capability, personnel competency/qualification, suitable equipment, product characteristics, release of product and services. Documented methods and procedures shall be established, maintained and approved.

Q-011 Certificate of Calibration

The calibrator service shall provide a certificate of calibration for each item calibrated. The certificate must include the date of calibration, readings "as received" and "after adjustment" if applicable, calibration due date, model and serial number of the equipment used in calibration and a statement that all equipment/standards used are traceable to the National Institute of Standards and Technology (NIST).

Q-012 Acceptance Test Plan

Acceptance testing shall be performed to the supplier's prepared ATP approved by Bigelow Aerospace. Requirements for design and development control, test, inspection, verification, use of statistical techniques for product acceptance, and as applicable critical items including key characteristics must be provided.

Q-013 Right of Access

Bigelow Aerospace, Bigelow Aerospace Customers and regulatory authorities have the right to access the facilities, all levels of the supply chain, all applicable records where the processing/manufacturing and assembly of the product is performed.



Quality Clauses F-740-006 Rev. J

Q-014 Standards of Workmanship

The supplier must maintain written standards of workmanship directly applicable to the nature and level of work performed under the Purchase Order. A copy shall be supplied upon request.

Q-015 Fracture Critical Control

The supplier shall comply with the requirements of all Flight and Fracture critical designated products. Changes in sequencing of manufacturing or any other substitutions are not allowed. The supplier must follow all instructions without deviations unless written permission is granted by Bigelow Aerospace.

Q-016 Surveillance

Designated representatives of regulatory authorities and the buyer including its direct or indirect customer shall have the right to review and monitor the quality system of the supplier. Bigelow Aerospace will coordinate with supplier, mandatory surveillance points. Supplier shall give Bigelow Aerospace reasonable notice prior to start of any processing, manufacturing or assembly relative to the purchase order. The supplier is expected to grant a designated representative access to the facility where the production of contracted items takes place.

Q-017 Source Inspection

Source Inspection is required for all materials and services supplied under this Purchase Order, prior to assembly and throughout all processing and testing. Evidence of source inspection must accompany each shipment.

Q-018 Nondestructive Inspection

Seller shall include with each shipment a certificate of inspection that list the Nondestructive inspections performed and must include the inspector's signature and stamp and Nondestructive test.

Q-019 <u>Destructive Analysis</u>

A part of suitable size and configuration for destructive analysis shall accompany each shipment made against this order. The part shall be the same material and shall have been processed with the lot it represents through all processes.



Quality Clauses F-740-006 Rev. J

Q-020 Government Source Inspection

Government Source Inspection is required prior to shipment from supplier's facility. On receipt of this order, promptly furnish a copy of this contract to the government representative. Evidence of government source inspection must be included with each shipment.

Q-021 First Article Inspection

First Article Inspection is required at supplier's facility. The First Article Inspection must be documented on form AS9102 or equivalent, so long as the equivalent form contains the same information required by AS9102.

First Article Inspection shall be performed on all new first production lots of a specific part number prior to shipment. New First Article Inspections are also required when any changes occur in characteristics or dimensions which affect the original First Article.

The report must accompany the identified part.

Q-022 <u>Digital Data</u>

Digital media / data must be controlled. Supplier must provide a Digital Data control plan for approval prior to receipt of data.

Q-023 Raw Material Test Reports

The original mill or foundry of chemical or physical test reports signed by authorized representative with title for material used in fulfilling this Purchase Order must be included. The lot number of each report must be traceable to the material. The test report must include objective evidence of compliance to the material's condition. Copies of each test report must be submitted with each shipment.

Q-024 Objective Evidence of Dimensional Inspection

Supplier shall provide objective evidence with each shipment that all goods furnished under this purchase order/contract were dimensionally inspected for compliance with drawing and other purchase order/contract requirements. Objective evidence shall consist of records of actual readings taken during the inspection of each part, with the dimension and its tolerance noted.

Q-025 Corrective Action

Acceptance of this contract or purchase order obligates the supplier to perform, upon request, a corrective action investigation when discrepant material is received. A written report shall be furnished, within a reasonable time period, which is specific and conclusive to prevent a reoccurrence of the discrepancy.



Quality Clauses F-740-006 Rev. J

Q-026 Supplier Product Nonconformance

Bigelow Aerospace must be notified whenever there is Nonconforming product, processes or services. Bigelow Aerospace must approve in writing, all Nonconforming dispositions.

Q-027 Certificate of Compliance

A Certificate of Compliance shall accompany all shipments. Certificate of Compliance must be signed by authorized representative with title. The COC must reflect all information necessary to identify the product, quantity, current revisions and all services or processes performed.

Q-028 Limited Life Material

When product includes using materials with a limited life, the supplier shall include the expiration date of the materials used and batch identification on the required certifications. If stipulated on the purchase order and/or contract, supplier will comply with shelf life requirements.

Q-029 Part Identification / Traceability

Method of Part identification must be approved by Bigelow Aerospace. Traceability is required on all raw materials to the manufacturer's source. Components need to be traceable to lot numbers during manufacturing.

Q-030 Packaging and Handling

As a minimum, the supplier must package all material in a manner that will ensure protection against corrosion, oxidation, deterioration and physical damage during shipment.

Q-031 Counterfeit Goods

Supplier shall not furnish to Bigelow Aerospace any Goods under this contract that are an unauthorized copy, imitation, substitute, or modified part (e.g., material, part, component), which is knowingly misrepresented as a specified genuine part of an original or authorized manufacturer.

Q-032 ITAR Registration

Seller shall comply with International Traffic in Arms Regulation §122.1, Registration requirements.



Quality Clauses F-740-006 Rev. J

Q-033 Records Retention

Suppler shall establish a documented procedure to define the controls needed for identification, storage, protection, retrieval, retention and disposition of records. Retain all item records pertaining to materials or services provided under this contract for a period of five (5) years (if not otherwise specified). Records include all forms of documented information.

Q-034 Safety and Health Plan

Supplier must maintain a Safety and Health Plan that addresses employee and subcontractor's safety and occupational health for work that is completely or partly on the supplier's premises, property owned or controlled by Bigelow Aerospace or the Government, and contracted offsite locations.

Q-035 Government Furnished Property

Supplier must maintain a Property Management Plan that adheres to the provisions of FAR 52.245-1 Government Property.

Q-036 Safety Data Sheet (SDS) / Safety Data Sheet (SDS)

A Safety Data Sheet (SDS) must accompany all shipments of this contract. In addition, if the supplier is aware of any additional precautions and/or handling requirements, the supplier is requested to submit those safeguards with the SDS.

Q-037 Certificate of Analysis

Supplier shall provide a Certificate of Analysis, ascertaining that a regulated product has met its product specification, quality, and has not degraded or become contaminated.

Q-038 Specifications

Unless otherwise noted, latest specification revisions apply.